



Refilling Instructions

For Canon BCI-61 Tri-Color Ink Tank
Contents:




Your BCI-61
Tri-Color Ink Tank


Refilling your cartridge is a clean and simple job, but it is advisable to cover your work area with scrap paper to protect from accidental spills.

Note: Empty chambers should be refilled as soon as they run out of ink to prevent the small amount of ink remaining in the cartridge from drying and hardening in the sponge.

1. Determine which of the three colors of ink are depleted by running a test print.




2. Remove the BCI-61 ink tank from the BC-61 cartridge and place on the table with the three ink ports facing up. See Figure A.



3. Uncap the ink bottle containing the color of ink that has been depleted.

4. Insert one of the syringes into the ink bottle until the tip of the syringe is submerged in ink. Draw 3cc of ink into the syringe. See Figure B.

Figure B



5. GENTLY touch the tip of the syringe to the ink port requiring refilling and slowly dispense the ink. If the ink starts to well up stop filling and allow time for it to soak in. Be careful to prevent ink from flowing over to one of the other ports. Stop filling if the port refuses to absorb more ink. See Figure C.




Figure C

IMPORTANT NOTE:
Do not allow colors to run from 1 port to another.

6. Repeat steps 4 and 5 two more times so that a total of 9cc of ink is dispensed into the ink chamber.
7. Put the ink tank back in the BC-61 cartridge. Reinstall in the printer and run a few cleaning cycles and a test print.

DO NOT REFILL ANY OTHER COLOR CHAMBER UNTIL IT IS DEPLETED!

IF YOU HAVE ANY QUESTIONS OR ENCOUNTER ANY DIFFICULTY IN USING THIS PRODUCT, PLEASE CONTACT:

REPEAT-O-TYPE
MANUFACTURING CORPORATION
ESTABLISHED 1931

665 State Highway 23 • Wayne, NJ 07470-6892 U.S.A. • (973) 696-3330 • (800) 288-3330
Fax: (973) 694-7287 • Email: help@repeatotype.com